BAKER HOSTETLER LLP EX PARTIE OR LATE FILED

Counsellors at Law

Washington Square, Suite 1100 • 1050 Connecticut Avenue, N.W. • Washington, D.C. 20036-5304 • (202) 861-1500 Fax (202) 861-1783 Mark Waldyry Com

WRITER'S DIRECT DIAL NUMBER

(202) 861-1624

February 18, 1998

RECEIVED

FEB 1 8 1998

FEDERAL COMMUNICATIONS COMMISSION OFFICE OF THE SECRETARY

VIA HAND DELIVERY

Ms. Magalie Roman Salas Secretary Federal Communications Commission 1919 M Street, N.W. Room 222 Washington, D.C. 20554

> Advanced Television Systems and Their Impact Upon the Existing Television Broadcast Service

MM Docket No. 87-268 Ex Parte Submission

Dear Ms. Salas:

Scripps Howard Broadcasting Company ("Scripps Howard"), through counsel, files two copies of this letter regarding the Commission's ongoing DTV allotment proceeding. Scripps Howard is the licensee of nine television stations, including Station KNXV-TV, Channel 15, Phoenix, Arizona. The Commission allotted Channel 14 as the DTV channel for Station KNXV-TV in the <u>Sixth</u> Report and Order (FCC 97-115, released April 21, 1997) in the above-captioned proceeding.

Scripps Howard filed a timely "Request for Clarification and Partial Reconsideration of the Fifth and Sixth Reports and Orders" on June 13, 1997 ("Petition for Reconsideration"). its Petition for Reconsideration, Scripps Howard noted its concern that the use of DTV Channel 14 in Phoenix will cause serious interference to land mobile radio facilities already in

 $^{^{1}}$ Scripps Howard is also the licensee of Stations KJRH(TV), Tulsa, Oklahoma; KSHB-TV, Kansas City, Missouri; WCPO-TV, Cincinnati, Ohio; WEWS-TV, Cleveland, Ohio; WMAR-TV, Baltimore, Maryland; and WPTV(TV), West Palm Beach, Florida. Scripps Howard's wholly owned subsidiaries are the licensees of Stations WFTS-TV, Tampa, Florida; and WXYZ-TV, Detroit, Michigan.

²A copy of the Petition for Reconsideration is attached.

Scripps Howard Broadcasting Company Page 2

use in the Phoenix metropolitan area.³ Scripps Howard explained that existing land mobile radio equipment operating on frequencies closest to 470 MHz would become useless, while the more than 200 land mobile licensees operating within 35 miles of the Station KNXV-TV transmitter would likely cause local interference to potential viewers of DTV Channel 14.⁴ Accordingly, Scripps Howard requested that an alternative DTV channel be allotted for Station KNXV-TV, and specifically proposed DTV Channel 56.⁵

Scripps Howard respectfully requests the Commission to consider its Petition for Reconsideration in conjunction with the numerous petitions for reconsideration of the <u>Sixth Report and Order</u> and the revised DTV Table of Allotments filed by the Association for Maximum Service Television, Inc. ("MSTV") on November 20, 1997. The threat of severe interference to land mobile licensees in the Phoenix metropolitan area, as well as to potential viewers of DTV Channel 14, described in the Petition for Reconsideration, still remains. Scripps Howard submits that the public interest would be disserved by the use of DTV Channel 14 and therefore renews its request for the use of DTV Channel 56, or an alternate channel determined by the Commission, in Phoenix.

Respectfully submitted,

Donald Zeifang Michael Ruger

cc: The Honorable William E. Kennard

The Honorable Susan Ness

The Honorable Gloria Tristani

The Honorable Harold Furchtgott-Roth

The Honorable Michael Powell

³Petition for Reconsideration at 1.

⁴Petition for Reconsideration at 1-2.

⁵Petition for Reconsideration at 2. Scripps Howard simultaneously filed a petition for rulemaking to amend the DTV Table of Allotments in the event the Commission does not modify the Station KNXV-TV DTV allotment in the course of MM Docket No. 87-268.

⁶The MSTV DTV Table of Allotments proposes the retention of DTV Channel 14 for Station KNXV-TV.

BAKER * HOSTETLER LLP

DATE STAMP & RETURN

COUNSELLORS AT LAW

WASHINGTON SQUARE, SUITE 1100 • 1050 CONNECTICUT AVENUE, N.W. • WASHINGTON, D.C. 20036-5304 • (202) 861-1500

FAX (202) 861-1783

WRITER'S DIRECT DIAL NUMBER

(202) 861-1728

June 13, 1997



VIA HAND DELIVERY

Mr. William F. Caton Acting Secretary Federal Communications Commission 1919 M Street, N.W. Room 222 Washington, D.C. 20554

Re: Advanced Television Systems and Their Impact Upon the Existing Television Broadcast Service (MM Docket No. 87-268)

Request for Clarification and Partial Reconsideration

Request for Clarification and Partial Reconside.

Dear Mr. Caton:

We are transmitting herewith on behalf of Scripps Howard Broadcasting Company a Request for Clarification and Partial Reconsideration of the <u>Fifth and Sixth Report and Orders</u> in the above-captioned proceeding. Please contact the undersigned if you have any questions.

Sincerely yours,

Michael Ruger

Enclosures

Before the FEDERAL COMMUNICATIONS COMMISSION Washington, D.C. 20554

In the Matter of)	
•)	
Advanced Television Systems)	
and Their Impact upon the)	MM Docket No. 87-268
Existing Television Broadcast)	
Service)	

TO: The Commission:

REQUEST FOR CLARIFICATION AND PARTIAL RECONSIDERATION OF THE FIFTH AND SIXTH REPORTS AND ORDERS

Submitted by: Scripps Howard Broadcasting Company

This Request for Clarification and Partial Reconsideration relative to the Fifth and Sixth Reports and Orders (RCPR) was prepared by Warren Happel, Vice President Engineering, Scripps Howard Broadcasting Company (SHBC). SHBC is the licensee of nine television stations consisting of six Very High Frequency (VHF) and three ULTRA High Frequency (UHF) facilities.

The Commission Staff accomplished a monumental task in preparing and writing the Fifth and Sixth Reports and Orders under the time constraints imposed. Now the task is to bring Digital Television (DTV) to the Public in a timely manner with service equal to, or better than, the Public now receives with NTSC. In support of the present task, this document is being submitted.

SPECIFIC CHANNEL CHANGE REQUEST FOR KNXV-TV PHOENIX AZ

In the Sixth Report and Order, APPENDIX B, DTV TABLE OF ALLOTMENTS, channel 14 is listed as the DTV channel for use with KNXV-TV's NTSC channel 15. SHBC is the licensee of KNXV-TV.

SHBC is very concerned that the use of channel 14 for DTV in Phoenix AZ, will cause serious interference to the Land Mobile Radio facilities already in-use in the Phoenix AZ metropolitan area. SHBC conducted a frequency search within 35 miles of the KNXV-TV proposed DTV transmitter site coordinates, for the frequencies of 469.5125 to 470 MHz (directly below channel 14). The results of this search are included as Exhibit 1 of the instant RCPR. Existing Land Mobile Radio equipment operating on frequencies closest to 470 MHz, (page 5 of Exhibit 1) would become useless due to front-end (pre-amplifier) overloading in the radio equipment, based on the experience of other channel 14 installations (Washington DC and Denver

Colorado for example). Additional filtering to the channel 14 DTV transmitted signal would not prevent front-end overloading. Activating channel 14 in areas where there is heavy lower adjacent channel Land Mobile activity (Phoenix AZ) would be unacceptable to the existing Land Mobile Licensees and not be in the best public interest.

Within 35 miles of the KNXV-TV transmitter, there are more than 200 Land Mobile Licensees operating on frequencies between 469.515 and 470 MHz. There is sure to be local interference from some of the Land Mobile operations to potential viewers of DTV channel 14. It is our understanding that interference from Land Mobile Licensees to the reception of channel 14 was not included in the FCC's prediction of interference to channel 14. However, interference would be present and prevent potential viewers from receiving the KNXV-TV DTV signal on channel 14. The interference would be fixed in areas of fixed site transmitters and random throughout the area from mobile radios.

A list of other available channels which could be considered for DTV by KNXV-TV at the DTV site coordinates was provided by the Association for Maximum Service Television (MSTV). The available channels for KNXV-TV at site coordinates 33° 20′ 00″, 112° 03′ 46″, were evaluated by examining each channel within the MSTV list according to the requirements of §73.623(d). The results of the evaluation are given in Table #1 below.

TABLE #1

MSTV LIST	CONSIDERTIONS OF CHANNELS WHICH MAY BE AFFECTED
31	DTV channel assigned in Tucson, 162.19 km separation.
47	Fourteen (14) channels above NTSC channel 33 in Phoenix.
54	Three channels above NTSC channel 51, 0.14 miles, separation; fifteen (15) channels above NTSC channel 39, a non-commercial assignment.
55	Four (4) channels above NTSC channel 51, 0.14 miles separation.
56	No considerations evident within 273.6 km, United States and Mexico (NTSC).
57	No considerations evident within 273.6 km, United States and Mexico (NTSC).
58	Seven (7) channels above NTSC channel 51, 0.14 miles separation; channel 58 application, Sierra Vista 285 km.
59	Eight (8) channels above NTSC channel 51, 0.14 miles separation.
63 through 69	Not in transition core spectrum, therefor not considered

Based on the forgoing considerations, SHBC requests that DTV channel 14, be changed to channel 56, (or another channel other than channel 14 as may be determined by the FCC) in the digital television table of allotments, PART 73 – RADIO BROADCAST SERVICES, specifically §73.622(b).

In the absence of other guidelines, SHBC will also be filing a Request for Rule Change with an identical request to change DTV channel 14 to DTV channel 56 in § 73.622(b) DTV Table of Allotments.

REQUEST TO RETAIN CHANNELS 2 THROUGH 6 FOR DTV:

SHBC requests channels two (2) through six (6) be retained for potential DTV use after the year 2006. This would provide time between now and 2006 for stations to evaluate the use of channels 2 through 6 for DTV. The Charlotte tests were limited in the evaluation of channel 6, and was the only low band VHF channel tested. The Charlotte tests appear to support the use of low band VHF channels for DTV.

REQUEST FOR CLARIFICATION OF DTV SERVICE CONTOURS

In APPENDIX B, DTV TABLE OF ALLOTMENTS of the Sixth Report and Order, the details were given which explain how the FCC determined the effective radiated power (ERP) assigned to the DTV allotments. The methodology employed by the FCC to pursue the goal of replicating "NTSC coverage" of a TV station which now uses an omnidirectional antenna seems to have resulted in the assignment of a directional antenna pattern (although not listed with the allotments) with the DTV allotment.

From APPENDIX B, DTV TABLE OF ALLOTMENTS, the following indented paragraphs were copied:

The tabulated value of effective radiated power (ERP) for DTV operation was calculated to replicate NTSC coverage. It is the maximum, over a set of uniformly spaced compass directions, of the ERP values required to extend noise-limited DTV coverage as far as the grade B contour of the NTSC station. This maximum is shown in the column entitled "DTV POWER." It is the basis for subsequent calculations of service and interference, and it was calculated using the following methodology:

The distance to the existing NTSC grade B contour was determined in each of 360 uniformly spaced compass directions starting from true north. This determination was made using information in the engineering data base, including directional antenna data, and using terrain elevation data at points separated by 3 arc-seconds of longitude and latitude. FCC curves (47 CFR §73.699) were applied in the usual way, as described in 47 CFR §73.684, to find this grade B contour distance, with the exception that dipole factor considerations were applied to the field strength contour specified in 47 CFR §73.683 for UHF.

Height above average terrain was determined every 5 degrees directly from the terrain elevation data, and by linear interpolation for compass directions in between. In cases where the TV Engineering Data Base indicated employment of a directional antenna, the ERP in each specific direction was determined through linear interpolation of the relative field values describing the directional pattern. (The directional pattern stored in the FCC computer data base provides relative field values at 10 degree intervals and may include additional values in special directions. The result of linear interpolation of these relative field values is squared and multiplied by the overall maximum ERP listed for the station in the TV Engineering Data Base to find the ERP in a specific direction.)

The replicating ERP for DTV was then calculated by a further application of FCC curves, with noise-limited DTV coverage defined as the presence of field strengths of 27.8, 35.8 and 40.8 dBµ respectively for low VHF, high VHF and UHF, at 50% of locations and 90% of the time. The specified field strengths have been calculated from the data given in Appendix A assuming that the value given there for receiver noise figure may be applied as a system noise figure including effects of electrical noise external to TV receivers. At UHF, the precise value 40.8 dBµ was applied for channel 38; and the value used for other UHF channels is 40.8 plus a dipole factor modification. This results in reception on channel 14 needing 2.3 dB less, and channel 69 needing 2.3 dB more, than the 40.8 dBµ for channel 38.

The dipole factor modification used in replication calculations is equal to 20 times log10 of the ratio of the center frequency of the UHF channel of interest to the center frequency of channel 38. For consistency, the same modification was applied to the grade B field strength contour for existing analogue UHF stations as specified in 47 CFR §73.683.

The power necessary to match (or replicate) the distance to the grade B contour with a DTV signal was computed for all 360 azimuths using the same radial-specific height above average terrain as for the NTSC case, but now in conjunction with F(50, 90) curves. The family of FCC propagation curves for predicting field strength at 50% of locations 90% of the time is found by the formula F(50, 90) = F(50, 50) - [F(50, 10) - F(50, 50)]. That is, the F(50, 90) value is lower than F(50, 50) by the same amount that F(50, 10) exceeds F(50, 50).

In general, these computations of DTV power to match the distance to the Grade B NTSC contour result in ERP values which vary with azimuth. For example, the azimuthal ERP pattern which replicates in UHF the Grade B contour of an omnidirectional VHF operation will be somewhat different because terrain has a different effect on propagation in the two bands. Thus, the procedure described here effectively derives a new directional antenna pattern wherever necessary for a precise match according to FCC curves.

(Note: Emphases added.)

It is not clear if the intention was to actually assign a directional DTV pattern with the DTV allotment or if the directional patterns were only developed to determine interference and allotments. If directional patterns are intended to be assigned with the allotments, some latitude will need to be permitted, such as plus or minus 1½ dB from the computed directional pattern. It would be very difficult, to perhaps impossible, for a manufacturer to build an antenna with a pattern that exactly replicates an antenna pattern developed from terrain contours. If an omnidirectional antenna were used with its pattern kept within the minimum power level of the directional pattern, service to the public would be seriously minimized. The use of directional DTV antennas would be further complicated with the installation of DTV antennas on the sides of existing towers, the only place available for many to be mounted during the tansistional period. The use of directional DTV antennas will also increase the delivery time for a given antenna.

With these concerns, SHBC requests clarification; Is the use of directional DTV patterns to replace omnidirectional patterns the intent or were the directional patterns only a tool used in the DTV allotment process?

PROTECTION OF SERVICE CONTOURS

During the transition period, stations should be protected to the Grade B contour for NTSC and the DTV

service area should be protected to the same contour. This will provide the public with the same (as near as

replication can make possible) service area for future DTV, as now defined for NTSC. To reduce the

protected service area for DTV to anything less than the present NTSC Grade B contour could prevent the

optimization of final DTV service to the public after the transition period. While interference during the

transition period is the inevitable result of the imposed channel packing density, the future DTV service to

the public should not be compromised. The present service NTSC service area (future DTV service area)

must be protected from any further reduction and interference during the transition period.

SUMMARY

Specifically in this RCPR, Scripps Howard Broadcasting Company requests that:

Channel 56 be substituted for channel 14 in the DTV allotment table for KNXV-TV, Phoenix AZ.

Channels 2 through 6 be retained for DTV use after the year 2006.

The use of directional DTV antennas be clarified.

The present NTSC Grade B contour also be the protected DTV service contour.

This RCPR prepared by SHBC lists only a few of the many concerns regarding the implementation of

DTV. Others, such as MSTV, will be submitting a longer list of concerns. Our collective purpose is

to deliver the best possible DTV service to the public, a purpose SHBC supports. To that end, Congress,

the FCC, and the Broadcasting Industry share the common goal of supporting a rapid but sensible transition

from NTSC to DTV. All of us will be learning more about DTV as we progress. The learning process

may, and likely will cause some implementation delays. Haste will not be an excuse for delivering less than

the best DTV service to the public.

Respectfully Submitted,

Scripps Howard Broadcasting Company

312 Walnut Street

Cincinnati, Ohio 45202

Warren Happel

Vice President Engineering

June 13, 1997

5

Frequency	Calisign	DBA Name	Transmitter Address	Transmitter	Latitude	Longitude	Elevation	ERP	Output	Distance
			,	City					Power	in Miles
469.512	WPHJ852	CHAMPION COMMUNICATION SERVICES IN	SOUTH MOUNTAIN	PHOENIX	331957	1120357	790.0	2.0	2.00	0.19
469.5125	KB74112	NORWEST BANK ARIZONA			332915	1120427		2.0	2.00	10.66
469.5125	WPCD246	BOHANNAN JR, ROBERT C	·		334430	1114300			2.00	34.50
469.5250	WNRX273	AGUA FRIA UNION HIGH SCHOOL	ATOP S MOUNTAIN	PHOENIX	332000	1120345	8110		40.00	0.02
469.5250	WNUQ205	COMPU TRONICS CORP	ATOP SOUTH MOUNTAIN	PHOENIX	332000	1120345	811 0		40.00	0.02
469.5250	WNMI465	EAGER BEAVER ENTERPRISES	ATOP SOUTH MOUNTAIN	PHOENIX	332000	1120345	811 0		40.00	0.02
469.5250	WNJD869	OBRIEN ELECTRIC	ATOP SOUTH MTN	PHOENIX	332000	1120345	811 0	5 0	5.00	0.02
469.5250	WNXQ754	THUNDERBIRD SAMARITAN HOSPITAL	ATOP SOUTH MOUNTAIN	PHOENIX	332000	1120345	811 0		40.00	0.02
469.5250	WNMI465	EAGER BEAVER ENTERPRISES	ATOP SOUTH MOUNTAIN	PHOENIX	331959	1120347	686.0		40 00	0.02
469.5250	WNUQ205	COMPU TRONICS CORP	ATOP SOUTH MOUNTAIN	PHOENIX	331959	1120547	686 0		40.00	1.94
469.5250	WPET824	SOUTH MOUNTAIN COMMUNITY COLLEGE	7050 S 24TH ST	PHOENIX	332330	1120200	343 0		4.00	4.37
469.5250	WNYC250	BANK OF AMERICA	1825 E BUCKEYE RD	PHOENIX	332640	1120224	335.0		4.00	7.78
469.5250	WNUQ205	COMPU TRONICS CORP	ATOP THE SIERRA ESTRELLA MOUNTAINS	AVONDALE	331624	1121648	1375.0		40.00	13.19
469.5250	WNBA867	ARIZONA BILTMORE RESORT	2400 E MISSOURI	PHOENIX	333131	1120100	393.0	0.0	25.00	13.51
469.5250	WPHW473	VIEWPOINT R V & GOLF RESORT	8700 E UNIVERSITY	MESA	332538	1115054	347.0		4.00	13.95
469.5250	WPIC944	SCOTTSDALE MARRIOTT SUITES		SCOTTSDALE	333008	1115532	381.0	0.0	4.00	14.08
469.5250	WPHZ797	CONAIR CORPORATION	7491 N GLEN HARBOR BLVD	GLENDALE	333100	1121700	324.0	0.0	2.00	17.93
469.5250	WNXQ754	THUNDERBIRD SAMARITAN HOSPITAL	ATOP SHAW BUTTE	PHOENIX	333546	1120526	671.0	ı	40.00	18.20
469.5250	WNUQ205	COMPU TRONICS CORP	ATOP SHAW BUTTE 1034 W SUNNYSIDE D	F PHOENIX	333554	1120513	649 0		40.00	18.34
469.5250	WNLJ430	RED MOUNTAIN RANCH COUNTRY CLUB	6450 E THOMAS RD	MESA	332855	1114124	463.0	ı	10.00	23.79
469.5250	WNRX273	AGUA FRIA UNION HIGH SCHOOL	ATOP WHITE TANK MOUNTAIN	PHOENIX	333409	1123333	1213.0	ı	40.00	32 89
469.537	WPJN837	KIRBLE ENTERPRISES			332105	1114623		0.0	0.05	16.75
469 537	WPJN435	MACSAN LLC			332515	1113924		0.0	0.05	24 17
469.5625	WPGZ667	MESA LUTHERAN HOSPITAL			332601	1115031	0.0)	1.00	14.48
469.562	WNVK264	TRW VEHICLE SAFETY SYSTEMS INC			331639	1113520	ı	2.0	2 00	27.60
469.5750	WNXH303	MEDTRONICS MICRO REL	2343 W 10TH PL	TEMPE	332505	1115837	347.0	1	4.00	7.66
469.5750	WNVD364	MARYVALE MALL	5220 W INDIAN SCHOOL RD	PHOENIX	332942	1121016			25.00	12.78
469.5750	WNRR494	PHOENICIAN RESORT	6000 E CAMELBACK	PHOENIX	333021				4.00	13.54
469.5756	WNMM350	THE WIGWAM	INDIAN SCHOOL RD & N LITCHFIELD RD	LITCHFIELD PARK	332943				5.00	20.19
469.5756	WPIX518	BUTTERFIELD STATION LANDFILL	40404 S 99TH AVE	MOBILE	330411				4.00	21 83
469.575	WNPE565	TOURNAMENT PLAYERS CLUB OF SCOTTS		SCOTTSDALE	333835				4.00	22.92
469.5756	WPGB280	TERRAVITA HOME CONSTRUCTION CO	BLACK MOUNTAIN	CAVE CREEK	334819				4.00	33.27
469.587	5 WPIG363	DOLLAR RENT	·		332557			0.0	2.00	7.18
469.600	WPAD257	ANR MANUFACTURING LTD	SOUTH MOUNTAIN	PHOENIX	331957				4.00	0.17
469.600	WNVM281	DOUBLETREE PARADISE VALLEY RESORT		PHOENIX	331957				4.00	
469.600	0 WNZN926	FARNSWORTH LESUEUR PROPERTY SERV	SOUTH MOUNTAIN	PHOENIX	331957					0.17
469.600	0 WNSM335	FELIX CONSTRUCTION COMPANY INC	SOUTH MOUNTAIN	PHOENIX	331957				4.00 25.00	0.17
469.600	0 WNVX616	INSIGHT INVESTIGATIONS	SOUTH MOUNTAIN	PHOENIX	331957				25.00	0.17
469.600	0 WNVH205	SCOTTSDALE CENTER FOR THE ARTS	SOUTH MOUNTAIN	PHOENIX	331957				4.00	0.17
469 612	5 KD31305	SOUTHWEST AIRLINES			332610				2.00	0.17
469.612	5 WPAL827	SCOTTSDALE CONFERENCE CENTER			333236			2.0	2.00	7.74
		,	Page 1 of 5			1110020	•	2,0	_	16.56 e - 6/12/97

File - Below141.dat, Frequency

Page 1 of 5
SCRIPPS HOWARD

Date - 6/12/97 EXHIBIT 1

Frequency (Callsign	DBA Name	Transmitter Address	Transmitter City	Latitude	Longitude	Elevation	ERP	Output Power	Distance in Miles
469 6125	WPJN837	KIRBLE ENTERPRISES		,	332105	1114623		0.0	0.05	16.75
469.6125	WPJN435	MACSAN LLC			332515	1113924		0.0	0.05	24.17
469.6250	KNNL711	JONES, M FRANKLYN	SOUTH MOUNTAIN	PHOENIX	331957	1120355	797.0	70.0	35.00	0.16
469.6250	KNNL711	JONES, M FRANKLYN	BANK ONE 201 N CENTRAL VE	PHOENIX	332703	1120420	331 0	70.0	35.00	8.13
469.6250	WQG854	MOTOROLA C & E INC	5005 E MC DOWELL RD	PHOENIX	332750	1115816	362 0	30.0	30.00	10.44
469.6250 (KNDY290	TRIAD TECHNOLOGY INC	ATOP SHAW BUTTE	PHOENIX	333539	1120512	648.0		40.00	18.05
469.6250	KNNL711	JONES, M FRANKLYN	WHITE TANK MOUNTAIN	PHOENIX	333409	1123333	1213.0	70.0	35.00	32.89
469.6375	WPHJ852	CHAMPION COMMUNICATION SERVICES I	N-SOUTH MOUNTAIN	PHOENIX	331957	1120357	790.0	20	2.00	0.19
469.6375	WNZM448	RESTAURA INC			332643	1120411			2.00	7.73
469.6500	WPHJ852	CHAMPION COMMUNICATION SERVICES I	N SOUTH MOUNTAIN	PHOENIX	331957	1120357	790.0	50.0	50.00	0 19
469.6500	WNFL984	COOLEY FOREST PRODUCTS	VALLEY NATIONAL BANK 241 N CENTRAL	PHOENIX	332703	1120420	331.0		35.00	8.13
469.6500	KNJH630	PENNINGTON INVESTIGATIONS INTERNA	TI VALLEY NATIONAL BANK 241 N CENTRAL	PHOENIX	332703	1120420	331.0	5.0	5.00	8.13
469 6625 \	WPHJ852	CHAMPION COMMUNICATION SERVICES I	N SOUTH MOUNTAIN	PHOENIX	331957	1120357	790.0	2.0	2.00	0.19
469.6625 \	WPFW356	TOYS R US			332654	1120424	0.0		0.10	7.96
469.6625 \	WPCC499	PINKERTON SECURITY SERVICES	•		332712	1120428			2 00	8.31
469.6625	WPGT905	AVNET INC			331822	1115029	0.0		2.00	12.90
469.6625	WPIR626	TOYS R US			333219	1121107		0.0	0.10	15.82
469.6625	WPIR716	TOYS R US			333120	1115414		0.0	0.10	15.92
469.6625	WPIV261	LOOKOUT MOUNTAIN GOLF COURSE	11111 N 7TH ST	PHOENIX	333517				2.00	17 58
469 6750 \	WNMP652	CONTINENTAL AIRLINES			332000	1120345			3.00	0.02
469.6750	KD38043	SHORENSTEIN CO PHOENIX PLAZA			331845				25.00	1 86
469.6750	KYW500	HYATT REGENCY HOTEL	122 N 2ND ST	PHOENIX	332659	1120416			4.00	8.05
469.6750	WPHZ797	CONAIR CORPORATION	7491 N GLEN HARBOR BLVD	GLENDALE	333100	1121700			2.00	17.93
469.6750	KNGR568	BUSINESS COMM CO OP	1014 W SUNNYSIDE DR	PHOENIX	333554	1120513			50.00	18 34
469.6750	WNYU920	BOULDERS RESORT	35015 N TOM DARLINGTON DR	CAREFREE	334801	1115502			2.00	33.29
469.6750	WPEE297	FRITO LAY	1450 MARICOPA HWY	CASA GRANDE	325357	1114733			40.00	33.79
469.6875	WNZM448	RESTAURA INC			332643				2.00	7.73
469.6875	WPGX939	GAINEY RANCH GOLF CLUB INC			332712				2.00	8.31
469.6875	WPJN837	KIRBLE ENTERPRISES			332105			0.0	0.05	16.75
469.6875	WPJN435	MACSAN LLC	·		332515			0.0	0.05	24.17
469.7000	WPCS202	A & B VINYL POOL SPECIALIST	ATOP SOUTH MOUNTAIN	PHOENIX	331957				4.00	0.16
469.7000	WNR\$864	BORG WARNER PROTECTIVE SERVICE	SOUTH MOUNTAIN	PHOENIX	331957				50.00	0.16
469.7000	KNJY474	CENTRAL TIRE INC	SOUTH MOUNTAIN	PHOENIX	331957				30.00	0.16
469.7000	WPCB580	EMM TRUCKING	ATOP SOUTH MOUNTAIN	PHOENIX	331957				4.00	0.16
469.7000	KNNW533	LINDEMAN, CHARLES R	SOUTH MOUNTAIN	PHOENIX	331957				35.00	
469.7000	KNGT687	JOE E WOODS INC	13208 S CENTRAL BLDG 12E	PHOENIX	331957					0.16
469.7000	KNNW533	LINDEMAN, CHARLES R	BANK ONE 201 N CENTRAL AVE	PHOENIX	332703				5.00 35.00	0.19
469.7000	KNNW533	LINDEMAN, CHARLES R	14 S 41ST PL	PHOENIX	332651				35.00 35.00	8.13
469.7000	KNNW533	LINDEMAN, CHARLES R	SIERRA ESTRELLA MOUNTAIN	PHOENIX	331624				35.00 35.00	8.89
469 7000	KNNW533	LINDEMAN, CHARLES R	SHAW BUTTE MOUNTAIN	PHOENIX	333539				35.00 35.00	13.12
469.7000	KNNW533	LINDEMAN, CHARLES R	WHITE TANK MOUNTAIN	PHOENIX	333409				35.00 35.00	18.05
ilo Dolou			Page 2 of 5		JJ-103	1123333	1213.0	70.0		32.89 6/12/9 - 3

File - Below141.dat, Frequency

Page 2 of 5
SCRIPPS HOWARD

Date - 6/12/97

EXHIBIT 1

Frequency	Calisign	DBA Name	Transmitter Address	Transmitter City	Latitude	Longitude	Elevation	ERP	Output Power	Distance in Miles
469.7125	WPID654	LIPPON L L C			332302	1115952		0.0	2.00	5.12
469.7125	WNZM448	RESTAURA INC			332643	1120411			2 00	7.73
469 7125	WPCC499	PINKERTON SECURITY SERVICES			332712	1120428			2.00	8.31
469.7125	WPIV261	LOOKOUT MOUNTAIN GOLF COURSE	11111 N 7TH ST	PHOENIX	333517	1120342	44.0	0.0	2.00	17.58
469.7125	WNAD728	MAC DOWALL COMMUNICATIONS	1014 W SUNNYSIDE DR	PHOENIX	333554	1120513	649.0		2.00	18.3
469.7125	WPGP761	CLUB TERRAVITA INC			334805	1115640	0.0		2.00	33.0
469.7250	WPCW242	RUSHMORE AIR CONDITIONING	13208 S CENTRAL BLDG 12-E	PHOENIX	331957	1120357	790.0		35.00	0.19
469.7250	WPBR699	WALMART STORES INC 6060	23701 W SOUTHERN AVE	BUCKEYE	332320			5.0	5.00	29.10
469.7250	WNAE292	ASSOCIATED FARMS	•		333409			50 0	15.00	32.8
469.7375	WNVJ453	SPECIALIZED COMMUNICATION CONSULTA	•		332712				2.00	8.3
	WPKH550	TECHNOLOGY DESIGN & CONSTRUCTION			331735			0.0	2 00	11.10
469.7375	WPJN837	KIRBLE ENTERPRISES			332105			0.0	0 05	16.7
	WPJN435	MACSAN LLC			332515			0.0	0.05	24.17
	WNYU368	BELL CONCRETE INC	ATOP SOUTH MOUNTAIN	PHOENIX	332003		808 0	0.0	100.00	0.1
469 7500	WPJM378	RESORT SUITES OF SCOTTSDALE		***************************************	332627		0000	0.0	4.00	10.8
	WNGB361	SOUTHWEST AMBULANCE INC	PHX INTERNATIONAL RACEWAY 11	S AVE A AVONDALE	332222		299.0	1100.0	110.00	14.7
	WNGB361	SOUTHWEST AMBULANCE INC	PHX INTERNATIONAL RACEWAY 11		332222			1100 0	110.00	14.7
469.7500	WNAW219	CONSOLIDATED WATER UTILITIES LTD	ATOP WHITE TANK MOUNTAINS 31		333409			1.000	40.00	32.8
		CONSOLIDATED WATER UTILITIES LTD	ATOP WHITE TANK MOUNTAINS 31		333409				40.00	32.8
	KNHX570	JUAREZ CONTRACTING INC	ATOP WHITE TANK MOUNTAINS	PHOENIX	333409				75.00	_
469.7625	WNZM448	RESTAURA INC			332643		12130			32.89
	WPGP761	CLUB TERRAVITA INC			334805	•	0.0		2.00 2.00	7.73
	WNMP652	CONTINENTAL AIRLINES			332000					33.00
469 7750	WPFC979	CHARLES SCHWABB INC	4701 E FRANCISCO DR	PHOENIX	331750				3.00	0.0
	WNVA969	RENAISSANCE SQUARE	2 N CENTRAL AVE	PHOENIX	332700				30.00	3.80
	WNWJ799	MARRIOTTS CAMELBACK INN	5402 E LINCOLN DR	SCOTTSDALE	333154			450.0	5.00	8.0
	WNDE694	DAVE BURCH CONSTRUCTION INC	ATOP SHAW BUTTE	PHOENIX	333554			150.0	50.00	14.9
	WNUL708	AMERICAN EXPRESS COMPANY	3151 W BEHREND DR	PHOENIX	334006				50.00	18.34
	WPIP589	GRAYHAWK GOLF CLUB	19600 N PIMA RD	SCOTTSDALE	334023		415.0	0.0	4.00	23.39
	WXQ815	APACHE JUNCTION UNIFIED SCHOOLS	2525 S IRONWOOD	APACHE JUNCTION				0.0	4.00	25.34
469.7875	WNZM448	RESTAURA INC		A ACIL JOHO HON	332643		307.0	30.0	30.00	29.21
469.7875	WPJN837	KIRBLE ENTERPRISES			332105			0.0	2.00	7.73
469.7875	WPJN435	MACSAN LLC			332515			0.0	0.05	16.75
	KNNS290	RAMIREZ, PETE	SOUTH MOUNTAIN	PHOENIX	331957		707.0		0.05	24,17
	KNNS247	SCHJANG SR, HANS V	SOUTH MOUNTAIN	PHOENIX	331957			70 O	35.00	0.16
		HEYNE, EARL	201 N CENTRAL AVE	PHOENIX				70.0	35.00	0.16
	KNNS290	RAMIREZ, PETE	BANK ONE 201 N CENTRAL AVE	PHOENIX	332703			70.0	35.00	8.13
	KNNS247	SCHJANG SR, HANS V	BANK ONE 201 N CENTRAL AVE	PHOENIX	332703			70.0	35.00	8,13
	KNNS290	RAMIREZ, PETE	14 S 41ST PL		332703			70.0	35.00	8,13
	KNNS247	SCHJANG SR, HANS V	14 S 41ST PL	PHOENIX	332651			70.0	35.00	8.89
	WPCV870	PEARCE & SONS DISTRIBUTING INC	SIERRA ESTRELLA MOUNTAIN	PHOENIX	332651		351.0	70.0	35.00	8.89
	2 · · · · ·		Page 3 of 4	KOMATKE 5	331115	1121215	1283.0	25.0	20 00 Date	12.95 6/12/9 -

File - Below141 dat, Frequency

Page 3 of 5 SCRIPPS HOWARD

Date - 6/12/97 EXHIBIT 1

Frequency	Callsign	DBA Name	Transmitter Address	Transmitter City	Latitude	Longitude	Elevation	ERP	Output Power	Distance in Miles
469 8000	KNNS290	RAMIREZ, PETE	SIERRA ESTRELLA MOUNTAIN	PHOENIX	331624	1121643	1375 0	70 0	35.00	13.12
469.8000	KNNS247	SCHJANG SR, HANS V	SIERRA ESTRELLA MOUNTAIN	PHOENIX	331624	1121643	1375.0	70 O	35 00	13.12
469.8000	WNMX567	MESA UNIFIED SCHOOL DISTRICT 4	2700 E BROWN RD	MESA	332424	1114602	366 0	35 O	35.00	17.77
469 8000	KNNS290	RAMIREZ, PETE	SHAW BUTTE MOUNTAIN	PHOENIX	333539	1120512	628.0	70.0	35.00	18.05
469.8000	KNNS247	SCHJANG SR, HANS V	SHAW BUTTE MOUNTAIN	PHOENIX	333539	1120512	628 0	70.0	35.00	18.05
469.8000	KNNS290	RAMIREZ, PETE	WHITE TANK MOUNTAIN	PHOENIX	333409	1123333	1213 0	70 O	35.00	32.89
469 8000	KNNS247	SCHJANG SR, HANS V	WHITE TANK MOUNTAIN	PHOENIX	333409	1123333	1213 0	70.0	35.00	32.89
469.8125	KD52295	CANYON STATE COMMUNICATIONS INC			332712	1120428	0.0		2.00	8.31
469.8125	WPDY231	RITZ CARLTON			333032	1120145			2 00	12.27
469.8125	WPGT905	AVNET INC			331822	1115029	0.0		2.00	12.90
469.8125	WPGP761	CLUB TERRAVITA INC			334805	1115640	0.0		2.00	33.00
469.8250	WNQN305	ARIZONA STATE UNIVERSITY	STADIUM DR	TEMPE	332518	1115545	366 0	i	4.00	9.82
469.8250	WPJS710	INSIGNIA COMMERCIAL GROUP	3300 N CENTRAL AVE	PHOENIX	332910	1120425	352 0	0.0	2.00	10.56
469.8250	WNJX561	PM REALTY GROUP	PHOENIX TOWNE HOUSE TOWER 100 W C	PHOENIX	332917	1120424	337.0	5.0	5.00	10.69
469.8250	WNJE625	MESA GOLFLAND INC	155 W HAMPTON	MESA	332429	1115031	376.0	ı	25.00	13.73
469.8250	WNGW394	JOHN C LINCOLN HOSPITAL SECURITY	JOHN C LINCOLN HOSPITAL	PHOENIX	333405	1120413	383 0	10 0	5.00	16.20
469.8250	KD40174	STONECREEK GOLF COURSE			333601			4 0	4 00	19.01
469 8375	WNZU557	A COMMUNICATIONS	•		332002				2.00	0.05
469.8375	WPJN837	KIRBLE ENTERPRISES			332105	1114623	,	0 0	0.05	16 75
469 8375	WPJN435	MACSAN LLC			332515	1113924		0 0	0 05	24.17
469 8500	WPK1782	ARNOT & ASSOCIATES			332339			0.0	4.00	6.72
469.8500	WQT423	MC CULLOUGH MOVE A HOME INC			332703	1120420)		50.00	8.13
469.8500	WPIK271	CHAMPION COMMUNICATION SERVICES IN	SHAW BUTTE	PHOENIX	333540	1120512	636.0	50 0	50.00	18 07
469.8500	WNVW503	CENTRAL ARIZONA REPEATER SERVICE	ATOP WHITE TANK MOUNTAIN	WADELL	333409	1123338	1250.0	ŧ	75.00	32.95
469.8625	WPCV332	SAFEWAY INCORPORATED			332543	1115530)		2.00	10.31
469.8625	WNVY894	MESA UNIFIED SCHOOL DISTRICT 4	USERY PASS	MESA	332936	1113826	762.0	20 0	2.00	26 71
469.8625	WPGP761	CLUB TERRAVITA INC			334805	1115640			2.00	33.00
469.8625	WPBS368	CENTRAL ARIZONA REPEATER SERVICE	ON TOP OF WHITE TANK MOUNTAINS	WADDELL	333440	1123424	1170.0)	2.00	33.89
469.8750	WNMP652	CONTINENTAL AIRLINES			332000	1120345			3.00	0.02
469.8750	WNUD854	ROUSE COMPANY	455 N 3RD ST	PHOENIX	332708	1120401	332.0)	4.00	8.21
469.8750	WNAB241	CHRISTOWN COMPANY	SOUTH MTN	PHOENIX	333120	1120539	350.0)	35.00	13.16
469.8750	WNPR820	PHOENICIAN RESORT	4701 N 64TH ST	SCOTTSDALE	333021	1115702	404.0	40	4.00	13 54
469.8750	KNJD347	RECREATIONAL CENTER INC	7800 E CAMELBACK RD	SCOTTSDALE	333015	1115435	380.0	50.0	25.00	14.72
469.8750	WPIP577	EL DORADO OF SUN CITY CONDOMINIUMS	10330 W THUNDERBIRD BLVD	SUN CITY	333621	1121709	335.0	0.0	4.00	22.77
469.8875	WPKJ889	VALLEY BANK TOWER			332003			0.0	2.00	0.11
469.8875	KD29963	DYNAIR FUELING INC			332608	1120105	,		2.00	7.51
469.9000	WPIN536	COBB, MICHAEL	201 N CENTRAL AVE	PHOENIX	332703			70.0	35.00	8 13
469.9000	KB37492	L&B INSTITUTIONAL PROPERTY MANAGER	2104 FIESTA MALL	MESA	332840				4.00	12 84
469.9000	WNBA867	ARIZONA BILTMORE RESORT	2400 E MISSOURI	PHOENIX	333131				25.00	13 51
469.9000	KKO258	A & S SHOTCRETE INC	USERY PASS	MESA	332936				50.00	26.71
469 9000	0 WNQQ483	HANDY PHONE	USERY PASS	MESA	332936				50.00	26.71
			Page 4 of 5							20.71 e - 6/12/91

File - Below141.dat, Frequency

SCRIPPS HOWARD

Date - 6/12/97 EXHIBIT 1

Frequency	Callsign	DBA Name	Transmitter Address	Transmitter	Latitude	Longitude	Elevation	ERP	Output	Distance
				City					Power	in Miles
469.9000	WIJ43	GILBERT PUMP & EQUIPMENT CO	ATOP WHITE TANKS MOUNTAIN	PHOENIX	333406	1123332	1212.0		75.00	32 84
469.9000	KKO258	A & S SHOTCRETE INC	WHITE TANKS	LITCHFIELD	333413	1123331	1213 0	150.0	50.00	32 90
469.9000	WNQQ483	HANDY PHONE	WHITE TANKS MOUNTAIN	LITCHFIELD	333413	1123331	1213.0	150.0	50.00	32.90
469.9125	5 WNWV351	OAK CANYON INC			332600	1120500			2.00	7 00
469.9125	5 WPBR299	SWANK AUDIO VISUALS INC			332712	1120428		0.0	2.00	8.31
469.9125	5 WPJN837	KIRBLE ENTERPRISES			332105	1114623		0.0	0.05	16.75
469.9125	5 WPJN435	MACSAN LLC			332515	1113924		0.0	0.05	24.17
469.912	WPGP761	CLUB TERRAVITA INC			334805	1115640	0 0		2 00	33.00
469.9250	WPJ\$710	INSIGNIA COMMERCIAL GROUP	3300 N CENTRAL AVE	PHOENIX	332910	1120425	352 0	0.0	2 00	10 56
469.9250	WSF345	CHANDLER UNIFIED SCHOOL DISTRICT 80	350 N ARIZONA AVE	CHANDLER	331826	1115050	369.0	75.0	75.00	12.56
469.9250	WPJN629	ORANGETREE RESORT	10601 N 56TH ST	SCOTTSDALE	333518	1115731	417 0	0.0	110 00	18.59
469.9250	WNUZ848	RAWHIDE OPERATING CO INC	23023 N SCOTTSDALE RD	SCOTTSDALE	334143	1115328	558.0	80.0	40 00	26.86
469.937	5 WPHJ852	CHAMPION COMMUNICATION SERVICES IN	SOUTH MOUNTAIN	PHOENIX	331957	1120357	790.0	2.0	2 00	0.19
469.9375	5 WPID654	LIPPON L L C			332302	1115952		0.0	2.00	5 12
469.9375	5 WNZP307	RESTAURA INC			332643	1120411		2.0	2 00	7.73
469.9375	5 KB37492	L&B INSTITUTIONAL PROPERTY MANAGER	2104 FIESTA MALL	MESA	332840	1115520	396 0	2.0	2 00	12 84
469.9375	5 WNUK229	AMES CONSTRUCTION INC	ATOP WHITE TANK MOUNTAINS	PHOENIX	333409	1123333	1213.0		2 00	32 89
469.9500	KD49273	HEITMAN PROPERTIES			331957	1120355		5 0	5 00	0.16
469.9500	WPBI566	MEEK PAINTING	ATOP SOUTH MOUNTAIN	PHOENIX	331957	1120355	808 0		40 00	0.16
469 9500	WPBI566	MEEK PAINTING	ATOP SOUTH MOUNTAIN	PHOENIX	331957	1120355	808.0		4 00	0 16
469.9500	WNZZ990	PROCLEAN INC	SOUTH MOUNTAIN	PHOENIX	331957	1120355	808.0	5.0	5 00	0 16
469.9500	WPHJ852	CHAMPION COMMUNICATION SERVICES IN	SOUTH MOUNTAIN	PHOENIX	331957	1120357	790.0	40.0	40 00	0.19
469.9500	WPHY649	HEYNE, EARL	201 N CENTRAL AVE	PHOENIX	332703	1120420	331.0	70.0	35.00	8.13
469.9500	WPJM378	RESORT SUITES OF SCOTTSDALE			332627	1115534		0.0	4.00	10.82
	WNUZ849	CRAIG SECURITY SERVICES	8 MI S OF 110 & ESTRELLA EXIT	GOODYEAR	332112	1122600	299.0		25 00	21.40
469.9500	WNBP454	FLETCHERS COBRE TIRE INC	ATOP WHITE TANK MOUNTAINS	PHOENIX	333409	1123333	1213.0		75.00	32 89
	0 KNFG676	L3X FARMS	ATOP WHITE TANK MOUNTAIN 30 MI W	PHOENIX	333409	1123333	1213 0		110 00	32.89
	WNKP592	P&L CAMBRON FARMS	ATOP WHITE TANKS MOUNTAINS	PHOENIX	333409	1123333	1213.0		5.00	32 89
_	5 WPHJ852	CHAMPION COMMUNICATION SERVICES IN	SOUTH MOUNTAIN	PHOENIX	331957	1120357	790.0	2.0	2.00	0 19
	5 WPID654	LIPPONLLC			332302	1115952		0.0	2.00	5.12
	5 WNZP307	RESTAURA INC			332643	1120411		20	2.00	7.73
_	5 WPJN837	KIRBLE ENTERPRISES			332105	1114623		0.0	0.05	16.75
	5 WPJN435	MACSAN LLC			332515	1113924		0.0	0.05	24 17
	0 WNML721	AMERICAN WEST AIRLINES INC	4000 E SKY HARBOR BLVD	PHOENIX	332408	1120206	343.0	20	2.00	5.02
	0 WNQN305		STADIUM DR	TEMPE	332518	1115545	366.0		4.00	9.82
		GRANCH GOLF CLUB INC	7281 E MOUNTAIN VIEW RD	SCOTTSDALE	333428		407.0		4.00	18.44
	0 WPES407	ARROWHEAD TOWNE CENTER	7700 W ARROWHEAD TOWNE CENTER	GLENDALE	333636	1121533	354.0		4 00	22.19
	0 WPCQ577	WARE PROPERTIES	2581 E STAGECOACH PASS	QUEEN CREEK	331242	1113216	462.0		40.00	31 43
409.987	5 WPID654	LIPPON L L C			332302	1115952		0.0	2.00	5.12

Page 5 of 5 SCRIPPS HOWARD